




ASSEMBLY INSTRUCTION




PART LIST




(A) x2




(B) x1




(C) x1




(D) x3




(E) x3




(F) x2




(G) x2




(H) x1



(J) x1




(K) x2



(L) x1

HARDWARES

1



Bolt M6x35mm = 20pcs

2



Bolt M6x20mm = 10pcs

3



Bolt M6x80mm = 6pcs

4







Washer M6 = 36pcs

5






Allenkey = 2pcs





A		2 PCS
B		1 PC
C		1 PC

2	 M6x20mm	4 PCS
4	 Washer M6	4 PCS
5	 Allenkey	1 PC

1








2




FINISH


x2





D		2 PCS
E		2 PCS
F		2 PCS
G		2 PCS
K		2 PCS

1	 M6x35mm	12 PCS
2	 M6x20mm	4 PCS
3	 M6x80mm	4 PCS
4	 Washer M6	20 PCS
5	 Allenkey	1 PC


1





x2



2





x2






3

x2








4

x2





FINISH





D		1 PC
E		1 PC
H		1 PC
J		1 PC
L		1 PC

1	 M6x35mm	8 PCS
2	 M6x20mm	2 PCS
3	 M6x80mm	2 PCS
4	 Washer M6	12 PCS
5	 Allenkey	1 PC



1





2





3





4



5



6



FINISH