




HC-016 Chest of 5 drawer








Parts supplied for assembly




PART DETAILS	CARTON BOX No.
1	1
2	1
3	1
4	1
5	2
6	1
7	1
8	1
9	1
10	1
11	1
12	2
13	1
14	5
15	5
16	5
17	5
18	5
19	5
20	1
21	1


Hardware supplied for assembly


[illegible]



101X6	102X6	103X1
		
L=40	Φ 15	



1







104X12	103X1
	
M6X30mm	









105X20	106X5	103X1
 $\Phi 4 \times 12 \text{mm}$	 L=300	








101X1	102X1	103X1
		
L=40	$\Phi 15$	








101X10	102X10	103X1	107X1
			
L=40	Φ 15		Φ 6X30mm






101X10	102X10	103X1	107X1
			
L=40	Φ 15		Φ 6X30mm




101X5	102X5	103X1
		
L=40	Φ 15	





8




10





17X5


105X30	106X5	103X1	110X30	107X10	111X30
	 106A  106B				
$\Phi 4 \times 12 \text{mm}$	L=300		$\Phi 12$	$\Phi 6 \times 30$	L=28


11



103X1	112X10	115X5
	 M4X25mm	


12






113X8	114X8
 $\Phi 3 \times 20 \text{mm}$	



14



116X1



103X1



117X2

 $\Phi 4 \times 14 \text{mm}$ 