
ASSEMBLY INSTRUCTIONS

Part List	ITEM CODE-281-016		
Label	Picture	Description	Qty.
1.		TOP	1 Pc.
2.		BASE	1 Pc.

HARDWARE LIST:


Label	Picture	Description	Qty.
Α		HEX NUT	4 Pcs.
В		WASHER	4 Pcs.
С	2=0	WRENCH	1 Pc.


STEP-1




Remove the hex nut and washer, as shown in image view.

STEP-2





STEP-4



COMPLETELY ASSEMBLED