





BED 1.8M

Parts supplied for assembly




PART DETAILS	CARTON BOX No.
1	5
2	5
3	4
4	4
5	3
6	4
7	2
9	4
10	3
11	4
12	1
13	1


Hardware supplied for assembly

101x 8	102x 8	103x 8	104x 4	105x 4	106x4	107x 2	108x6	109x6	110 x 6	111 x 9	112 x 12	113 x 40
14X12	Φ42X5	M8	M8X120	Φ8.5/Φ20X1.5	M8X80	M6X60	Φ14	M6X75	M6, L=15	Φ5X70	Φ4×40	Φ4×25
114x 4	115x 4	116x 4	117 x 8	118 x 12	119 x 8	120x 1	121 x 1					
M6X30	Φ6.5/Φ20X1.5	M6	M6X45 (附带自配)	M6X20 (附带自配)	Φ6X30							


Note: Skipping any steps could lead to improper assembly and damages.
Do not tighten the bolts before finishing all steps.




Step 1



Step 2



Parts




① x 2




② x 6

Parts



⑩ x 1



⑪ x 2



⑫ x 1

Hardware

117 x 8



M6X45
(附赠自配)

Hardware

112 x 12




φ 4 x 40

108 x 6




Φ 14


Step 3




Parts




Hardware



Step 4




Parts




Hardware




Step 5




Parts



Hardware




Step 6




Parts


Hardware



Step 7




Parts




Hardware




Step 8




Parts




Hardware



Step 9




Parts



Hardware

Step 10



Parts

Hardware