





herbert 100 dressing table




herbert 100 dressing table




| | |
|---|---|
| 107x20 | 108x4 |
|  |  |
| Φ 4X12mm | M6X25mm |

herbert 100 dressing table


1






| |
|---|
| 116X2 |
|  |
| Φ 8X40mm |

herbert 100 dressing table


2






| | | |
|---|---|---|
| 101x7 | 102x7 | 119x1 |
|  |  |  |
| Φ 15*12mm | 7*32.5mm | Φ 7X50mm |

herbert 100 dressing table


3





| | | |
|---|---|---|
| 101x7 | 102x7 | 107x3 |
|  |  |  |
| Φ 15*12mm | 7*32.5mm | Φ 4X12mm |

herbert 100 dressing table


4






| | |
|---|---|
| 101x2 | 102x2 |
|  |  |
| Φ 15*12mm | 7*32.5mm |

herbert 100 dressing table


5





| | | |
|---|---|---|
| 101x2 | 122x2 | 105x2 |
|  |  |  |
| Φ 15*12mm | 5*32.5mm | Φ 6X30mm |

herbert 100 dressing table


6





| | |
|---|---|
| 101x2 | 102x2 |
|  |  |
| Φ15*12mm | 7*32.5mm |

herbert 100 dressing table


7



| | |
|---|---|
| 101x2 | 102x2 |
|  |  |
| Φ15*12mm | 7*32.5mm |

herbert 100 dressing table

8




107x3



Φ 4X12mm

herbert 100 dressing table

9



101x3

102x3




Φ 15*12mm



7*32.5mm

herbert 100 dressing table

10




119x2



Φ7X50mm

herbert 100 dressing table

11



101x5



Φ15*12mm


102x5





7*32.5mm

herbert 100 dressing table


12









| | |
|---|---|
| 101x3 | 102x3 |
|  |  |
| Φ 15*12mm | 7*32.5mm |

herbert 100 dressing table


13





| | | | |
|---|---|---|---|
| 110x2 | 111x2 | 120x2 | 105x4 |
|  |  |  |  |
| M6X35mm | M6X50mm | Φ 14X12 | Φ 6X30mm |
| 101x4 | 102x4 | | |
|  |  | | |
| Φ 15*12mm | 7*32.5mm | | |



herbert 100 dressing table

14



| | |
|---|---|
| 106x8 | 108x2 |
|  |  |
| Φ 4X16mm | M6X25mm |

herbert 100 dressing table




109x4



M6X30mm




herbert 100 dressing table

16














herbert 100 dressing table

| | | | |
|----------|----------|----------|----------|
| 103x4 | 104x4 | 105x2 | 112x2 |
| | | | |
| Φ12*10mm | 5*19.5mm | Φ6X30mm | φ 10 |
| 117x1 | 114x1 | 107x4 | 113x2 |
| | | | |
| M4X25mm | | Φ 4X12mm | Φ 5X50mm |



herbert 100 dressing table

| | | | |
|---|---|---|---|
| 103x8 | 104x8 | 105x4 | 112x4 |
|  |  |  |  |
| Φ 12*10mm | 5*19.5mm | Φ 6X30mm | φ 10 |
| 117x2 | 114x2 | 107x8 | 113x4 |
|  |  |  |  |
| M4X25mm | | Φ 4X12mm | Φ 5X50mm |



herbert 100 dressing table

| | | | |
|-----------|----------|----------|----------|
| 103x12 | 104x12 | 105x12 | 112x6 |
| | | | |
| Φ 12*10mm | 5*19.5mm | Φ 6X30mm | φ 10 |
| 117x3 | 114x3 | 107x12 | 113x6 |
| | | | |
| M4X25mm | | Φ 4X12mm | Φ 5X50mm |

