



TEST REPORT

Report No. 010126070116

DATED: 04 AUGUST 2026

Client : KEPPEL WOOD INDUSTRIES (M) SDN BHD
POS 541, 6 ½ MILES, KESANG, 84000 MUAR, JOHOR

Buyer : PACIFIC 18 LIMITED

Sample Description : TWIN OVER DODUBLE BUNK BED FRAME

Item No. : WHITE

SKU No. : 816-013

Model / Style : 816-013

Production Date : JULY 2026

Age Grade : /

Manufacturer : KEPPEL WOOD INDUSTRIES (M) SDN BHD

Country of Origin : MALAYSIA

Country of Destination : AUSTRALIA/NEW ZEALAND

Test Sample Received : RECEIVED ON 08/07/2026

Test Period : FROM 08/07/2026 TO 03/08/2026

TEST REQUESTED	CONCLUSION	REMARK
AS/NZS 4220:2010 – BUNK BEDS AND OTHER ELEVATED BEDS	PASS	/

Remark(s):

The results reported herein have been performed in accordance with the terms of accreditation under the Singapore Accreditation Council.

For technical enquiries or any other concerns,
please contact:

GIC TESTING & INSPECTION SERVICES PTE LTD

Tel: +65 6741 2260

Email: services.sg@gicgrp.com

PREPARED BY:

LUKMAN YUSOFF

Testing Engineer

APPROVED BY:

WONG KOK LEONG

Assistant Lab Manager

GIC Testing & Inspection Services Pte Ltd

158 Kallang Way, #08-01,
Singapore 349245





Report No. 010126070116

DATED: 04 AUGUST 2026

SAMPLE PHOTO



GICG - ENABLING TRUST IN A CHANGING WORLD




Report No. 010126070116

DATED: 04 AUGUST 2026

SAMPLE PHOTO



WARNING LABEL



PRODUCT LABEL



Report No. 010126070116

DATED: 04 AUGUST 2026

TEST RESULT(S):

AS/NZS 4220: 2010 - Bunk Beds and Other Elevated Beds

Test Method : Reference to AS/NZS 4220:2010

Clause	Content	Results
4	Materials	
4.1	Timber	NA
4.2	Metals	M
4.3	Coatings and plastics components	NR
5	Construction	
5.1	General	M
5.2	Fasteners	M
5.3	Play and other integrated features	M
5.4	Maximum height	M
5.5	Minimum distance between beds	M
5.6	Mattress support elements (mattress base components)	M
5.7	Safety barriers	
5.7.1	General	M
5.7.2	Guardrails	M
5.8	Climbing access	
5.8.1	General	M
5.8.2	Rungs and Steps (Treads)	M
5.8.3	Grip for access devices	M
5.9	Tube end openings	NA
5.10	Sharp edge and sharp points	M
5.11	Protrusions and snag points	M
6	Safety and performance requirements	
6.1	Entrapment hazard	M
6.2	Stability	M
6.3	Fastenings of upper bed to the lower supporting structure	M
6.4	Fatigue test on joints	M
6.5	Impact test	M
6.6	Static load on guardrails	M
6.7	Impact load on guardrails	M
6.8	Access device attachment	M
6.9	Static load on treads	M
6.10	Impact load on treads	M
7	Information leaflet	M
8	Marking	
8.1	General	M
8.2	Marking legibility	M
8.3	Marking durability	M

Note: The samples were tested in accordance with the test methods in Appendices A through J whenever applicable

M = Meet NM = Not Meet NA = Not Applicable NT = Not tested R = Refer to Comment Section

NR = Not Requested



Report No. 010126070116

DATED: 04 AUGUST 2026

END OF REPORT

This report sets forth our findings solely with respect to the test samples identified herein. The results in this report are not representative of the quality or characteristics of the lot/batch from which a test sample was taken or any similar or identical product unless specifically and expressly noted. The sample/s mentioned in this report is/are submitted/supplied/manufactured by the Client, GIC Testing & Inspection Services Pte. Ltd. therefore assumes no responsibility for the accuracy of information on the brand name, model/ style number, consignment or any information supplied. Unless otherwise stated in this report, no tests were conducted to determine long term effects of using the specific product. Any copying or replication of this report to or for any other person or entity, or use of our name or trademark, is permitted only with our prior written permission.

GICG - ENABLING TRUST IN A CHANGING WORLD